

# Sterilization

The sterilization of Volara® and VolaraBLOCK® by Ethylene Oxide is not recommended. The combination of temperature and vacuum has occasionally demonstrated dramatic shrinkage in this material.

When sterilization is required, radiation sterilization is recommended.